



www.vman-engine.com



Shanghai VMAN engine Co.,Ltd
 Building102-202, Zone E10, Bay Valley II,
 No.1566 Guoquan Rd(N)
 Shanghai , 200438

8000 hours maintenance spareparts 2023 (CE10 Series)

Marks	Parts		Unit Qty	Unit Price	8000H
			Each Engine Demand	USD	
Per 200 hours should replace(or 6 month if instock)	Oil filter element 机油滤芯	95.04302-6001-7	2	US\$29.5	80
Per 500 hours should replace	Air filter element 空滤芯	AA02960 00JX	1	US\$270.2	16
	Fuel fine filter cartridge 燃油精滤芯	95.1250.5018A-2	1	US\$41.8	16
	Oil water separator 油水分离器	95.12303-5005	1	US\$35.0	16
Per 1000 hours should replace	Fan belt 风扇皮带	628DJ1025001A	1	US\$10.4	8
	Generator belt 发电机皮带	618DA1025001C	1	US\$21.6	8
Per 2000 hours should checked, need be replace if broken	Pressor And Temperature Sensor进气压力温度传感器部件	618DA3611007A	1	US\$32.6	4
	Coolant-Temp-Sensor水温传感器部件	618DA3611005A	1	US\$8.3	4
	Oil Pressure Temperature Sensor 机油压力温度传感器	618DA3611004A	1	US\$57.7	4
	Crankshaft Position Sensor 曲轴转角传感器	618DA3611002A	1	US\$14.7	4
	Torsion damper扭转减振器	618DA1005201A	1	US\$199.6	4
Per 2400 hours should replace	Tensioner 张紧轮部件	618DA1025002A	1	US\$73.4	3
	Fan Tensioner 风扇张紧轮部件	618DB1025002A	1	US\$62.2	3
Per 3000-4000 hours should checked, need be replace if broken	Intake valve 进气阀	618DA1007001A	12	US\$8.4	24
	Exhaust valve 排气阀	618DA1007002A	12	US\$12.2	24
	Bearing upper connecting rod 连杆上瓦	618DA1004010A	6	US\$12.8	12
	Bearing lower connecting rod 连杆下瓦	618DA1004011A	6	US\$4.4	12
	Connecting rod assembly 连杆组件	618DA1004002A	6	US\$104.8	12
	Thermostat element 节温器部件	S618DD1306000A	2	US\$11.9	4
Per 6000-8000 hours should checked, need be replace if broken	Piston 活塞	618DA1004101A	6	US\$87.7	6
	Piston Pin 活塞销	618DA1004107A	6	US\$12.8	6
	Piston ring (2nd) 第二气环	618DA1004103A	6	US\$4.7	6
	Piston ring (1st) 第一气环	618DA1004102A	6	US\$10.3	6
	Piston ring (Oil) 活塞环	618DA1004104A	6	US\$5.4	6
	Oil cooler assembly 机冷器部件	618DA1013001B	1	US\$428.7	1
More than 9000 hours should checked, need be replace if broken	Crank shaft 曲轴	618DA1005002A	1	US\$1,316.2	1
	Main Bearing (Upper) 主轴瓦 (上)	618DA1002024A	7	US\$5.6	7
	Main Bearing (Lower) 主轴瓦 (下)	618DA1002025A	7	US\$5.6	7
Need checked and replace when it broken	Sealing Cylinderhead Cover气缸盖罩密封条	618DA1003208A	1	US\$17.5	1
	Gasket cylinder head 气缸盖垫片	618DA1003100A	1	US\$103.4	1
	Oil cooler gasket 机冷器垫片	618DA1013011A	1	US\$0.5	1
	Starter 起动机部件	618DA3708001A	1	US\$514.3	1
	Altern 发电机部件	618DA3701001B	1	US\$257.2	1
	Common Rail Pump Assy 电控燃油泵	618DB1123001A	1	US\$1,411.3	1
	As Oil Pump 机油泵部件	618DA1011001A	1	US\$231.6	1
	Water-Circulation Pump 水泵部件	S618DB1307001A	1	US\$492.1	1
	Exhaust manifold center 排气歧管中段	618DA1008101A	1	US\$74.8	1
	Exhaust manifold -front&rear排气歧管前后段	618DA1008103A	2	US\$56.1	2
	Exhaust manifold gasket排气歧管垫片	618DA1008105A	6	US\$7.8	6
	STUD BOLT M10X30双头螺柱M10	618DA1008111B	4	US\$3.4	4





www.vman-engine.com



Shanghai VMAN engine Co.,Ltd
 Building102-202, Zone E10, Bay Valley II,
 No.1566 Guoquan Rd(N)
 Shanghai , 200438

8000 hours maintenance spareparts 2023 (CE12 Series)

Marks	Parts		Unit Qty	Unit Price	8000H
			Each Engine Demand	USD	
Per 200 hours should replace(or 6 month if instock)	Oil filter element 机油滤芯	95.04302-6001-7	2	US\$29.5	80
Per 500 hours should replace	Air filter element 空滤芯	AA02960 00X	1	US\$270.2	16
	Fuel fine filter cartridge 燃油精滤芯	95.1250.5018A-2	1	US\$41.8	16
	Oil water separator 油水分离器	95.12303-5005	1	US\$35.0	16
Per 1000 hours should replace	Fan belt 风扇皮带	628DJ1025001A	1	US\$10.4	8
	Generator belt 发电机皮带	628DA1025001C	1	US\$23.2	8
Per 2000 hours should checked, need be replace if broken	Pressor And Temperature Sensor进气压力温度传感器部件	618DA3611007A	1	US\$32.6	4
	Coolant-Temp-Sensor水温传感器部件	618DA3611005A	1	US\$8.3	4
	Oil Pressure Temperature Sensor 机油压力温度传感器	618DA3611004A	1	US\$57.7	4
	Crankshaft Position Sensor 曲轴转角传感器	618DA3611002A	1	US\$14.7	4
	Torsion damper扭转减振器	628DA1005201A	1	US\$214.0	4
Per 2400 hours should replace	Tensioner 张紧轮部件	618DA1025002A	1	US\$73.4	3
	Fan Tensioner 风扇张紧轮部件	618DB1025002A	1	US\$62.2	3
Per 3000-4000 hours should checked, need be replace if broken	Intake valve 进气阀	628DA1007001A	12	US\$8.1	24
	Exhaust valve 排气阀	628DA1007002A	12	US\$11.5	24
	Bearing upper connecting rod 连杆上瓦	628DA1004010A	6	US\$12.7	12
	Bearing lower connecting rod 连杆下瓦	628DA1004011A	6	US\$4.4	12
	Connecting rod assembly 连杆组件	628DA1004002A	6	US\$121.3	12
	Thermostat element 节温器部件	618DD1306000A	2	US\$11.9	4
Per 6000-8000 hours should checked, need be replace if broken	Piston 活塞	628DA1004101A	6	US\$106.2	6
	Piston Pin 活塞销	628DA1004107A	6	US\$14.5	6
	Piston ring (2nd) 第二气环	628DA1004103A	6	US\$5.4	6
	Piston ring (1st) 第一气环	628DA1004102A	6	US\$11.5	6
	Piston ring (Oil) 活塞环	628DA1004104A	6	US\$5.8	6
	Oil cooler assembly 机冷器部件	628DA1013001C	1	US\$463.5	1
More than 9000 hours should checked, need be replace if broken	Crank shaft 曲轴	628DA1005002A	1	US\$1,436.3	1
	Main Bearing (Upper) 主轴瓦 (上)	628DA1002024A	7	US\$5.5	7
	Main Bearing (Lower) 主轴瓦 (下)	628DA1002025A	7	US\$5.5	7
Need checked and replace when it broken	Sealing Cylinderhead Cover 气缸盖罩密封条	628DA1003208A	1	US\$21.6	1
	Gasket cylinder head 气缸盖垫片	628DA1003100A	1	US\$90.3	1
	Oil cooler gasket 机冷器垫片	628DA1013011A	1	US\$0.5	1
	Starter 起动机部件	618DA3708001A	1	US\$514.3	1
	Altern 发电机部件	618DA3701001B	1	US\$257.2	1
	Common Rail Pump Assy 电控燃油泵	628DB1123001A	1	US\$1,512.7	1
	As Oil Pump 机油泵部件	628DA1011001A	1	US\$234.0	1
	Water-Circulation Pump 水泵部件	628DB1307001A	1	US\$498.4	1
	Exhaust manifold center 排气歧管中段	628DA1008101A	1	US\$74.4	1
	Exhaust manifold -front&rear排气歧管前后段	628DA1008103A	2	US\$58.1	2
	Exhaust manifold gasket排气歧管垫片	628DA1008105A	6	US\$8.2	6
	STUD BOLT M10X30双头螺栓M10	618DA1008111B	4	US\$3.4	4





www.vman-engine.com



Shanghai VMAN engine Co.,Ltd
 Building102-202, Zone E10, Bay Valley II,
 No.1566 Guoquan Rd(N)
 Shanghai , 200438

8000 hours maintenance spareparts 2023 (CE13 Series)

Marks	Parts		Unit Qty	Unit Price	8000H
			Each Engine Demand	USD	
Per 200 hours should replace(or 6 month if instock)	Oil filter element 机油滤芯	95.04302-6001-13L	2	US\$29.5	80
Per 500 hours should replace	Air filter element 空滤芯	AA02960 00JX	1	US\$270.2	16
	Fuel fine filter cartridge 燃油精滤芯	95.12503-5018A-13L	1	US\$41.8	16
	Oil water separator 油水分离器	95.12303-5005	1	US\$35.0	16
Per 1500hours should replace	Fan belt 风扇皮带	630DA1025001A	1	US\$78.5	5
Per 2400 hours should replace	Tensioner 张紧轮部件	630DA1025002A	1	US\$88.8	5
Per 2000 hours should checked, need be replace if broken	Pressor And Temperature Sensor进气压力温度传感器部件	618DA3611007A	1	US\$32.6	4
	Coolant-Temp-Sensor水温传感器部件	618DA3611005A	1	US\$8.3	4
	Oil Pressure Temperature Sensor 机油压力温度传感器	618DA3611004A	1	US\$57.7	4
	Crankshaft Position Sensor 曲轴转角传感器	618DA3611002A	1	US\$14.7	4
	Torsion damper扭转减振器	630DA1005201A	1	US\$228.2	4
Per 3000-4000 hours should checked, need be replace if broken	Intake valve 进气阀	628TA1007001A	12	US\$30.8	24
	Exhaust valve 排气阀	628TA1007002A	12	US\$26.8	24
	Bearing upper connecting rod 连杆上瓦	630DA1004010A	6	US\$22.1	12
	Bearing lower connecting rod 连杆下瓦	630DA1004011A	6	US\$5.8	12
	Connecting rod assembly 连杆组件	630DA1004002A	6	US\$114.4	12
	Thermostat element 节温器部件	S618DD1306000A	2	US\$11.9	4
Per 6000-8000 hours should checked, need be replace if broken	Piston 活塞	630DA1004101A	6	US\$222.2	6
	Piston Pin 活塞销	630DA1004107A	6	US\$17.8	6
	Piston ring (2nd) 第二气环	630DA1004103A	6	US\$5.7	6
	Piston ring (1st) 第一气环	630DA1004102A	6	US\$17.4	6
	Piston ring (Oil) 活塞环	630DA1004104A	6	US\$9.3	6
	Oil cooler assembly 机冷器部件	630DA1013001B	1	US\$654.6	1
More than 9000 hours should checked, need be replace if broken	Crank shaft 曲轴	630DA1005002A	1	US\$1,393.4	1
	Main Bearing (Upper) 主轴瓦 (上)	630DA1002024A	7	US\$6.9	7
	Main Bearing (Lower) 主轴瓦 (下)	630DA1002025A	7	US\$6.9	7
Need checked and replace when it broken	Sealing Cylinderhead Cover气缸盖罩密封条	628DA1003208A	1	US\$21.6	1
	Gasket cylinder head 气缸盖垫片	630DA1003100A	1	US\$89.4	1
	Oil cooler gasket 机冷器垫片	630DA1307025A	1	US\$11.8	1
	Starter 起动机部件	618DA3708001A	1	US\$514.3	1
	Altern 发电机部件	630DA3701001A	1	US\$257.2	1
	Common Rail Pump Assy 电控燃油泵	628DE1123001A	1	US\$1,768.0	1
	As Oil Pump 机油泵部件	630DA1011001A	1	US\$248.1	1
	Water-Circulation Pump 水泵部件	S630DF1307001A	1	US\$166.0	1
	Exhaust manifold center 排气歧管中段	628DJ1008101A	1	US\$88.4	1
	Exhaust manifold -front&rear排气歧管前后段	628DA1008103A	2	US\$58.1	2
	Exhaust manifold gasket排气歧管垫片	628DA1008105A	6	US\$8.2	6
	STUD BOLT M10X30双头螺栓M10	618DA1008111B	4	US\$3.4	4

